

WORKERS' COMPENSATION BOARD

INDUSTRIAL HYGIENE DEPARTMENT

Telephone 266-0211 Telex 04-507765 5255 Heather Street. Vancouver, B.C., V5Z 3L8

January 10, 1975

Association of University and College Employees Local No. 1 2162 Western Parkway Vancouver 8, B. C.

Dear Sirs:

Enclosed is a copy of Inspection Report No. 750004 issued to the University of British Columbia, Woodward Biomedical Laboratory on January 9, 1975.

Yours truly,

N. D. Heaslip Supervising Industrial Hygienist Industrial Hygiene Department DECIVED JAN 14 1975

A. U. C. E.

Encl.

NDH:mm

GQ Inspection F	WORKMONS COMPONSATION BOARD & BUILS 5255 Haather Street. Vancouver 13, BC. Telephone 266-0211, Telex 04-507765	33E5 0 8 1 1 1 E	Firm Loc. Class Ind. Page 1 of 2 Woodward Biomedical Laboratory The University of British Columbia
			L
			r.
Act the Board	with requirements of the Workmen's Compensation directs that one copy of this statement be posted in place at or near the operation inspected.		The University of British Columbia Point Grey Campus Columbia Vancouver, B. C.
Portion inspect	ted Circulation Area on		JAN 14 1975
October 1	, 1974 and January 6, 1975		
Portion Inspec	ted appears to conform to the requirements of the ention Regulations (except as noted)		A. U. C. E.
A lightin	g survey was conducted on these visi	ts to i	nspect the quality and
	of the lighting in relation to the v		
in the circulation department. Accident Prevention Regulation 8.44 applies.			
Results:			
1. Visual tasks are a major portion of the activities of the workers in this			
area. Materials read include much finely printed material such as indices			
and r	educed computer print outs.		and the second
			Le succhity of lighting
2. With the exception of the basement Xerox area, the quantity of lighting			
is adequate to the visual tasks in all areas inspected. This includes			
the areas illuminated by the continuous lines of 2 tube, 4 foot, recessed,			
ceiling, delux white, fluorescent tubes with diffuser shields in the			
circulation central area and the morgue and mail room in the basement.			
	asement Xerox area is inadequately] e visual tasks.	lighted	with 7 to 10 foot candles
			Continued
		MODIO	MEN'S COMPENSATION BOARD
		WORK	Serien Heart
	January 9, 1975 Per	G. Hew	
Date	January 9, 1975 Per		Industriat Hygienist

1

1

7

1

Address all communications to the Director, Industrial Hygiene Department. Please quote your firm number and inspection report number on all correspondence.

Important: You are required to correct the health hazards specified above without delay and within two weeks notify the Board in writing of action taken. Special assessment rates or other penalties may be applied for failure to comply with orders of the Board.

Continued form IR. 750004

Page 2 of 2

Results: Continued

4. Contrasts in the light intensity of the visual fields are not excessive with the possible exception of the general open area where the workers are required to look up at long unbroken lines of luminaires. Even here complaints of eye strain are likely the natural consequence of heavy visual tasks rather than lighting faults. Complaints of sore eyes are more predominant in the workers exposed in the open area.

Recommendations:

- 1. The poor lighting in the basement Xerox area can probably be corrected by the use of a student lamp or other suitable table lamp placed on top of the machine as discussed.
- 2. Some type of drop-board or other shield might be employed to break the visual effect of the long line of bright luminescence which workers in the open area are subject to in glancing up to check the situation at the service counter.

INSTRUCTIONS:

Order #1 The lighting in the basement Xerox area shall be increased to a minimum of 70 foot candles on the work surfaces as specified for reading or transcribing tasks in offices.

Sandin Hewitto

G. Hewitt Industrial Hygienist Industrial Hygiene Department GH:mm